STOLL
THE RIGHT WAY TO KNIT

Pattern No.: 1010112 - Yarn Quality V-Teil(e)

A	B	C	D	E	D	C	B	A
Friction >	>>	8A, FOG| 2x Nm 24 | Zero torque | 100% WV | Michell |		8		8A| - | - | Residual yarn | - | - |	<	Friction <
Friction >	>	7A, FOG| 1x Nm 24 | Zero torque | 100% WV | Michell |		7		7B,FOG| 3x Nm 24 | Zero torque | 100% WV | Michell |	<<<	Friction <
Friction >	>>	6A, LEAF| 2x Nm 100/4 | BPM0771 | 100% CO | BROS |		6				
				5		5A, FOG| 1x Nm 24 | Zero torque | 100% WV | Michell |	<	Friction <
				4		4A, LEAF| 2x Nm 100/4 | BPM0771 | 100% CO | BROS |	<<	Friction <
				3		3A, FOG| 2x Nm 24 | Zero torque | 100% WV | Michell |	<<	Friction <
	>	2A| - | - | Comb thread | - | - |		2				
Friction >	>	1A| - | - | Draw separation thread | - | - |		1				

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track

 Normal  Intarsia type 1  Intarsia type 2  Plating Yf. N  Double-Arm Plating Yf.  Plating_w_2->1  Plating_w_2->2

Pattern No.: 1010112 - Yarn Quality R-Teil(e)

A	B	C	D				E	D			C	B	A
							8				8A| - | - | Residual yarn | - | - |	<	Friction <
Friction >	>	7A, FOG| 1x Nm 24 | Zero torque | 100% WV | Michell |					7				7B, FOG| 3x Nm 24 | Zero torque | 100% WV | Michell |	<<<	Friction <
Friction >	>>	6A, LEAF| 2x Nm 100/4 | BPM0771 | 100% CO | BROS |					6						
							5				5A, FOG| 1x Nm 24 | Zero torque | 100% WV | Michell |	<	Friction <
							4				4A, LEAF| 2x Nm 100/4 | BPM0771 | 100% CO | BROS |	<<	Friction <
							3				3A, FOG| 2x Nm 24 | Zero torque | 100% WV | Michell |	<<	Friction <
	>	2A| - | - | Comb thread | - | - |					2						
Friction >	>	1A| - | - | Draw separation thread | - | - |					1						

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track

Normal Intarsia type 1 Intarsia type 2 Plating Yf. N Double-Arm Plating Yf. Plating_w_2->1 Plating_w_2->2