STOLL
THE RIGHT WAY TO KNIT

Pattern No.: 1010105 - Yarn Quality V-Teil(e)

A	B	C	D	E	D	C	B	A
Friction >	>	8A| - | - | Residual yarn | - | - |		8		8B| - | - | Residual yarn | - | - |	<	Friction >
Friction >	>	7A, FUCHSIA| 1x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |		7				
Friction >	>	6A, FOG| 1x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |		6				
Friction >	>>	5A, FOG| 2x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |		5				
				4		4A, FOG| 1x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |	<	Friction <
				3		3A, FOG| 2x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |	<<	Friction <
	>	2A| - | - | Comb thread | - | - |		2		2A, FUCHSIA| 1x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |	<	Friction <
Friction >	>	1A| - | - | Draw separation thread | - | - |		1				

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track

Normal Intarsia type 1 Intarsia type 2 Plating Yf. N Double-Arm Plating Yf. Plating_w_2->1 Plating_w_2->2

Pattern No.: 1010105 - Yarn Quality R-Teil(e)

A	B	C	D	E	D	C	B	A
Friction >	>	8A| - | - | Residual yarn | - | - |		8		8B| - | - | Residual yarn | - | - |	<	Friction >
Friction >	>	7A, FUCHSIA| 1x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |		7				
Friction >	>	6A, FOG| 1x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |		6				
Friction >	>>	5A, FOG| 2x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |		5				
				4		4A, FOG| 1x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |	<	Friction <
				3		3A, FOG| 2x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |	<<	Friction <
	>	2A| - | - | Comb thread | - | - |		2		2A, FUCHSIA| 1x Nm 48/2 | CT-3869 | 68% CO, 32% PES | Svaco |	<	Friction <
Friction >	>	1A| - | - | Draw separation thread | - | - |		1				

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track

Normal Intarsia type 1 Intarsia type 2 Plating Yf. N Double-Arm Plating Yf. Plating_w_2->1 Plating_w_2->2