









Pattern No.: 0310523 / E210IF18 - Yarn Quality V-Teil(e)

A	B	C	D	E	D	C	B	A
				8				
	-	7A - Elastic thread -						
	-	6A 1x 30/1 Nm Vispa / rot 75% VI, 25% PA BSA Schaefer						
				5			5A - Elastic thread -	
				4			4A 1x 30/1 Nm Vispa / rot 75% VI, 25% PA BSA Schaefer	
	-	3A 1x 30/1 Nm Vispa / weiss 75% VI, 25% PA BSA Schaefer						
	-	2A - Comb thread -		2			2B 1x 30/1 Nm Vispa / weiss 75% VI, 25% PA BSA Schaefer	
	-	1A - Draw separation thread -			1			

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track



Normal



Normal-ADF



Intarsia type 1



Intarsia type 2



Plating Yf. N



Double-Arm Plating Yf.



Plating_w_2->1



Plating_w_2->2

Pattern No.: 0310523 / E210IF18

Other Requirements:

Rapportschalter 2 und 3 wurden nach Technikdurchlauf eingefügt. Verwendung von Elasthanfaden für Biese notwendig
