









Pattern No.: 0610050 - Yarn Quality Kragen

A	B	C	D	E	D	C	B	A
				8		8A - Residual yarn -	<	Friction <
				7				
				6				
				5				
				4				
				3		3A, LIGHT BLUE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing	<<<	Friction <
	>	2A - Comb thread -		2				
Friction >	>	1A - Draw separation thread -		1				


A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track
















Pattern No.: 0610050 - Yarn Quality Zubehör

A	B	C	D	E	D	C	B	A
				8		8A - Residual yarn -	<	Friction <
				7				
				6				
				5				
				4				
				3		3A, LIGHT BLUE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing	<<<	Friction <
	>	2A - Comb thread -		2				
Friction >	>	1A - Draw separation thread -		1				


A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track









Pattern No.: 0610050 - Yarn Quality V-Teil(e)

A	B	C	D	E	D	C	B	A
Friction >	>>>	8A, WHITE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing		8		8B - Residual yarn -	<	Friction <
Friction >	5 >	7A, BLUE 5x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing		7		7B, WHITE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing	<<<	Friction <
Friction >	>>>	6A, BLUE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing		6				
Friction >	>>>	5A, LIGHT BLUE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing		5		5B, WHITE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing	<<<	Friction <
Friction >	>	4A - Residual yarn -		4		4B, BLUE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing	<<<	Friction <
				3		3A, LIGHT BLUE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing	<<<	Friction <
	>	2A - Comb thread -		2		2B, BULE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing	<<<	Friction <
Friction >	>	1A - Draw separation thread -		1				

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track



Pattern No.: 0610050 - Yarn Quality R-Teil(e)

A	B	C	D	E	D	C	B	A		
				8				8A - Residual yarn -	<	Friction <
Friction >	5 >	7A, BLUE 5x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing		7						
Friction >	>>>	6A, BLUE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing		6						
				5						
				4				4A, BLUE 3x 30/2 Ne Q7-06 50% CO, 50% MD Ningbo Qiaotaixing	<<<	Friction <
				3						
	>	2A - Comb thread -		2						
Friction >	>	1A - Draw separation thread -		1						

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track

