

Pattern No.: 0310584 / D031T14 - Yarn Quality Tandem left Kragen_1

A	B	C	D	E	D	C	B	A
				8				
				7				
	V	6A - Draw separation thread -			6			
				5				
				4		4A - Residual yarn -	V	
				3		3A 3x 3x Nm 64/2 Brasil - Otto	VV	
				2		2A 3x 3x Nm 64/2 Brasil - Otto	VV	
				1				

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track

 Normal
  Normal-ADF
  Intarsia type 1
  Intarsia type 2
  Plating Yf. N
  Double-Arm Plating Yf.
  Plating_w_2->1
  Plating_w_2->2

Pattern No.: 0310584 / D031T14 - Yarn Quality Tandem right Kragen_1

A	B	C	D	E	D	C	B	A
				8				
				7				
	V	6A - Draw separation thread -			6			
				5				
				4		4A - Residual yarn -	V	
				3		3A 3x 3x Nm 64/2 Brasil - Otto	VV	
				2		2A 3x 3x Nm 64/2 Brasil - Otto	VV	
				1				

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track



Normal



Normal-ADF



Intarsia type 1



Intarsia type 2



Plating Yf. N



Double-Arm Plating Yf.



Plating_w_2->1



Plating_w_2->2