





Pattern No.: 0310588 / D034T14 - Yarn Quality Tandem left Kragen_1

A	B	C	D	E	D	C	B	A
				8				
				7				
	V	6A - Draw separation thread -						
				5				
				4		4A - Residual yarn -	V	
				3		3A - Residual yarn -	V	
				2		2A 2x Nm 53/2 - Gebrüder Otto	VV	
				1				

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track



Normal



Normal-ADF



Intarsia type 1



Intarsia type 2



Plating Yf. N



Double-Arm Plating Yf.



Plating_w_2->1



Plating_w_2->2