





Pattern No.: 0810519 - Yarn Quality Leibteil(e)

A	B	C	D	E	D	C	B	A		
				8				8A - - Residual yarn - -	<	
				7						
				6						
				5						
				4				4A 2x Nm 48/2 Tango 85% CO, 10% SE, 5% WS YSK	<<	Friction <
				3						
	>	2A - - Comb thread - -		2						
	>	1A - - Draw separation thread - -		1						

A: Feed Wheel B: Feed C: Yarn count D: Feeder E: Track

